Fire Safety Assessment Report



Manila Chemical Company

2 No. Jungle Latifpur, Jafrabad, Akbar Shah, Shitakundo, Chittagong.

Date of Assessment: 27th & 28th February, 2021

Date of Report: 1st March, 2021

Report Code: FSA-70 Report Version: 1.0



Author: Md. Jamil Miah

Reviewer: Md. Masud Kamal



Table of Contents

Executive Summary	1
Distribution of checkpoints	2
General Information	4
Location and Co-ordinates	4
Exterior View of Factory Building	5
Factory Information	6
Factory Layouts	8
Detailed Observations of Non-conformities	9
Evacuation Pathway	10
Stairways	16
Discharge Level	20
Fire Separation	22
Safety Systems	27
Management	40
DIFE Summary	44
Recommendations for Corrective Action	44
Disclaimer	47



1

Executive Summary

A survey of the existing fire safety condition was undertaken at the **Manila Chemical Company**, on **27**th **& 28**th **February**, **2021** by AIPRO Engineering & Consultancy Service. The survey was conducted as per Bangladesh National Building Code 2020 and other relevant Standards.

There are 5 structures in the factory premises namely: Production Shed, Office Building, Godown Shed-1, Godown Shed-2, Godown Shed-3. Total usable area of the factory was 4,956 square feet.

During the assessment, the fire safety system of the building was assessed for 67 checkpoints to form an opinion regarding the level of compliance with respect to Bangladesh National Building Code 2020 and other relevant Standards. Major issues of fire safety assessment are mentioned below:

- The factory shall maintain a minimum width of evacuation pathways (i.e. evacuation passageway 1.12m in storage area and 0.915m in other areas) as per code.
- The factory will remove all temporary stored items from evacuation pathways & ensure all evacuation pathways shall be free from temporary stored item.
- The factory shall remove all locking devices from evacuation exits.
- Emergency lighting was not provided for evacuation pathway.
- Chemical stores shall be fire separated by rated wall and rated door as per code.
- The factory shall prepare design drawings for the fire detection and alarm system in accordance with the code and install the fire detection and alarm systems as per code.
- Fire drill shall be conducted as detailed under the fire safety plan. The frequency of fire drill shall be as per BNBC Table 4.A.1.



Distribution of Checkpoints

The checkpoints were categorized as below, based on the timeline of implementation and the risk they possess. The following table and pie-chart show the distribution of checkpoints for the factory.

	TABLE 1: DISTRIBUTION OF CHECKPOINTS					
SI. No	Priority Level	Implementation Timeline	No. of non- complianc es	% share		
1	Immediate	The facility should not continue to occupied until these non-compliances have been rectified	0	0%		
2	1-2 Weeks	Action must be incorporated into a fire safety management plan in 1-2 Weeks	11	16%		
3	6 Weeks	Action (remedy work indicated) must be carried out within period of 6 Weeks	13	19%		
4	6 Months	Action (remedy work indicated) must be carried out within period of 6 Months	9	14%		
5	Compliant	No corrective action required	9	14%		
6	Not Applicable	These checkpoints were not applicable to the factory	25	37%		
	Total Check Points 67 100%					






Figure-1: Distribution of Checkpoints

The non-compliances have been prioritized based on the timeline in which the corrective action can be implemented. As seen above, there are **0**% non-compliances which need immediate action. Corrective actions for **16**% of non-compliances need to be implemented in Short term (1-2 Week), whereas **19**% of non-compliances need Mid-term (6 Weeks) for corrective action. **14**% of checkpoints fall under Long term (6 months) category for corrective action. There are **14**% of checkpoints which show general compliance with Bangladesh National Building Code 2020 and other relevant Standards.



General Information

TABLE 2: GENERAL INFORMATION			
Factory Name & Address	Manila Chemical Company 2-no Jungle Latifpur, Jafrabad, Shitakundo, Chattogram.		
Factory License Number	2630/Chattogram		
Date of Inspection	27 th & 28 th February, 2021		
Name of Factory Managing Director	Md. Delowar Hossain		
Factory Concern Person Name	Md. Rejaul Karim		
Phone number of Contact Person	+88 01928812683		
Email Address of Contact Person	mdrejaulkarim1920@gmail.com		


Location Map

Co-ordinates: Latitude [22.37921° N] Longitude [91.77305° E]





Exterior View of Factory Building







Factory General Information

•						
TABLE 3: BUILDING INFORMATION						
Building Name	Floor Designation	Area in sft (Floor- wise)	Occupancy Type (Floor- wise)	Type of Construction	Building Height	Construction History
Production Shed (Single Storied)	Ground Floor	1006	J2, H2	Non-rated Shed	17'-0"	2008
Office Building (Single Storied)	Ground Floor	358	E	RCC	9'-0"	2020
Godown Shed-1 (Single Storied)	Ground Floor	1232	J2	Non-rated Shed	11'-6"	2008
Godown Shed-2 (Single Storied)	Ground Floor	2000	J2	Non-rated Shed	22'-0"	2016-2017
Godown Shed-3 (Single Storied)	Ground Floor	360	H2, J2	Non-rated Shed	9'-0"	2016-2017



7


	TABLE 4: MEANS OF EGRESS							
Building Name	Floor Designation	No. of Existing Occupants (Floor- wise)	No. of Stair	No. of exit	Req. total width of exit (mtr.) BNBC Table 4.3.2	Measured total width of exit doors (mtr.)	Req. total width of exit stairs (mtr.) BNBC Table 4.3.2	Measured total width of exit stairs (mtr.)
Production Shed (Single Storied)	Ground Floor	5	NA	1	0.02	1.2	NA	NA
Office Building (Single Storied)	Ground Floor	3	NA	3	0.012	2.43	NA	NA
Godown Shed- 1 (Single Storied)	Ground Floor	0	NA	1	-	2.88	NA	NA
Godown Shed 2 (Single Storied)	Ground Floor	0	NA	1	-	4	NA	NA
Godown Shed- 3 (Single Storied)	Ground Floor	0	NA	2	-	1.7	NA	NA

Note: The factory shall maintain minimum width of exit door 1.0 meter as per BNBC- 3.9.3, Page 2890 and also maintain minimum width of stair as per BNBC-Table 4.3.6.


NA: Not Applicable



Factory Layout









Detailed Observations of Non-conformities

The non-conformities have been categorized into following sections. Detailed observations of non-conformities are listed in the relevant sections. Against each non-compliance, the timeline for implementing corrective actions is mentioned on the top-right corner of every point. The summary of the no. of checkpoints in every section against the non-compliances is given in the table below.

Section	No. of checkpoints	No. of non- compliances
Evacuation Pathway	9	5
Stairways	11	0
Discharge Level	3	1
Fire Separation	9	3
Safety Systems	28	22
Management	7	2
Total	67	33



Evacuation Pathway

1	Have all evacuation pathways the minimum required width in accordance with the Guideline?	1-2 Weeks
Section	Evacuation Pathway	
Description	During the assessment, we did not find minimum width of evacusome area like - exit door of Office Building: 0.81m, passageway Shed: 0.66m, exit door of Godown Shed-3: 0.85m, etc.	•
Corrective Action Plan	The factory shall maintain the minimum width of passageways, industrial area (Occupancy: G1, G2) and 0.915 m for storage are area (Occupancy: H1, H2, J) at the evacuation pathways as per c	a, high hazardous
Reference	BNBC-3.8.3, Page- 2889 and Table 4.3.8 in Page 2902	
Pictorial Evidence		

2	Are all evacuation pathways free of any permanent obstacles?	Compliant
Section	Evacuation Pathway	
Description	During the assessment, we found no permanent obstacles at the evacuation pathways.	
Corrective		
Action Plan		
Reference	BNBC- D.7.3, Page- 2812 and Sec 3.4.5 in Page 2884	



3	Are all evacuation pathways free of any temporary stored items?	1-2 Weeks	
Section	Evacuation Pathway		
Description	During the assessment, temporary stored items were found in evacuation pathways. Location: Production Shed, Godown Shed-1, Godown Shed-2, etc.		
Corrective Action Plan	The factory will remove all temporary stored items from evacuation pathways & ensure all evacuation pathways shall be free from temporary stored item.		
Reference	BNBC- D.7.3, Page- 2812 and Sec 3.4.5 in Page 2884		
Pictorial Evidence			

4	Do all evacuation ramps comply with the maximum allowable slope?	NA
Section	Evacuation Pathway	
Description	Ramps were not available in the factory during the assessment.	
Corrective		
Action Plan		
Reference	BNBC- 3.11.1 and 3.11.3	



5	Does the maximum travel distance from any location of the floor to nearest emergency exit meet the requirement of code?	Compliant
Section	Evacuation Pathway	
Description	During the assesment we found the following maximum travel of 1. Production Shed = 16m. 2. Godown Shed-1 = 15m. 3. Godown Shed-2 = 19.5m. As per above mesurement, the maximum travel distances meet the Code.	
Corrective Action Plan		
Reference	BNBC- Table 4.3.4 and Table 4.3.8	

6	Do all floor exit doors and final exit doors swing in the direction of travel?	6 Weeks	
Section	Evacuation Pathway		
Description	Exit doors were not swing in the direction of travel and have slid Location: Production Shed, Godown Shed-1, Godown Shed-2, et	=	
Corrective Action Plan	The factory shall ensure to change existing exit doors on evacuation routes, exit doors with side hinged type door, which swing outward and in the direction of travel.		
Reference	BNBC- 3.9.5, Page- 2890		
Pictorial Evidence			



7	Do the doors in the egress route open easily? Doors cannot be locked at any time in the direction of evacuation.	6 Weeks
Section	Evacuation Pathway	
Description	During the assessment, the doors in the egress route open easily locking features were found at building exits, egress routes and Location: Production Shed, Godown Shed-1, Godown Shed-2, et	exit discharge.
Corrective Action Plan	Remove all locking device from all egress doors. All exit doors sh from the side they serve without the use of a key.	nould be open-able
Reference	BNBC- 3.4.3, Page- 2884	
Pictorial Evidence		



8	Is the width of emergency exits satisfactory?	6 Weeks
Section	Evacuation Pathway	
Description	During the assessment, the width of emergency exits was not satisfactory. Exit door of Office Building = 0.8m Exit door of Godown Shed-3 = 0.85m	
Corrective Action Plan	Factory shall ensure the emergency exits minimum 1 meter per exit as per code.	
Reference	BNBC- 3.9.3, Page- 2890	
Pictorial		
Evidence		* 6 S 100 60 60 60 60 60 60 60 60 60 60 60 60 6



9	Does the sum of the width of all emergency exits meet the requirement in accordance with the number of occupants?	Compliant
Section	Evacuation Pathway	
Description	TABLE 4: MEANS OF EGRESS, the sum of width of exits meet the accordance with the number of exiting occupants. However, the factory shall maintain minimum width of exits 1 m	·
Corrective Action Plan		
Reference	BNBC- Table 4.3.2, Page- 2887	



Stairways

10	Does the number of exits is adequate based on No of occupants per floor?	Compliant
Section	Stairways	
Description	During the assesment, we found the following information: 1. Office Building (i) Ground floor = Total occupant 3, Total exit 3. 2. Production Shed (i) Ground floor =Total occupant 5, Total exit 1. 3. Godown Shed-1 (i)Ground floor=Total occupant 0, Total exit 1. The maximum travel distances of the Production Shed and Godo 16m and 15m respectively. As per above data, the number of exbased on No. of occupants per floor.	
Corrective Action Plan		
Reference	BNBC- 3.14.2, 3.14.3, Table 4.3.4 Page 2890-2891	

11	Does the minimum width of stairs meet the requirement of code?	NA
Section	Stairways	
Description	During the assessment, no stair was available in the factory. So this issue is not applicable.	
Corrective Action Plan		
Reference	BNBC-Table 4.3.6, Bangladesh Labour Rules, 2015, Rules: 54(7)	



12	Does the sum of the width of all staircases meet the requirement in accordance with BNBC?	NA
Section	Stairways	
Description	There was no stairway in the factory premises.	
Corrective		
Action Plan		
Reference	BNBC- Table 4.3.2, Page- 2887	

13	Are handrails provided in all stairways?	NA
Section	Stairways	
Description	There was no stairway in the factory premises.	
Corrective		
Action Plan		
Reference	BNBC- 3.10.4, Page- 2895 and 3.10.8 in Page 2897	

14	Is the tread/riser relationship consistent on all stairways?	NA
Section	Stairways	
Description	There was no stairway in the factory premises.	
Corrective		
Action Plan		
Reference	BNBC- Table 4.3.5, Page- 2893 and 3.10.6, Page- 2896, 1.14.5.2 Page 2651	



15	Are internal stairways linking more than two floors fire separated with fire rated walls?	NA
Section	Stairways	
Description	During the assessment, internal stairways were not available in the factory.	
Corrective Action Plan		
Reference	BNBC- Table 3.3.1 (a) in Page 2749	

16	For stairs that require fire separation, are they provided with fire rated self-closing doors?	NA
Section	Stairways	
Description	There was no stairway in the factory premises.	
Corrective		
Action Plan		
Reference	BNBC- Table 3.3.1 (a) and Table 3.2.3 and 5.9.2 (c) in Page 2936	5

17	For stairs that require fire separation (such as high rise buildings, >33m height or >10 floors), are they provided with fire rated entry lobby?	NA
Section	Stairways	
Description	Maximum measured height was 6.7 meter at Godown Shed-2. There was not high rise building in the factory premises.	
Corrective Action Plan		
Reference	BNBC- 3.13.4, Page- 2900 and 5.9.2 (c) in Page 2936	



18	Are stairways free of any obstacles?	NA
Section	Stairways	
Description	There was no stairway in the factory premises.	
Corrective Action Plan		
Reference	BNBC- D.7.3, Page- 2812	

19	Are stairways free of any combustibles?	NA
Section	Stairways	
Description	There was no stairway in the factory premises.	
Corrective Action Plan		
Reference	BNBC- D.7.3, Page- 2812, Best Practice	

20	Is proper protection (e.g. fire rated barriers) provided for exterior stairs so that the exit path is not obstructed?	NA
Section	Stairways	
Description	Exterior Stairs were not available during the assessment.	
Corrective Action Plan		
Reference	BNBC- 3.10.11, Page-2898	



Discharge Level

21	Is discharge floor exit/Premises exit widths based on the number of occupants and minimum allowable width?	Compliant
Section	Discharge Level	
Description	During the assesment we found the following information: Total occupant = 12 Total floor area = 460.4 square meters. Total design occupant load = 46 Required premises exit width = 0.23 meters Measured premises exit width = 4.5 meters As per above information, premises exit widths based on existing occupant load meets the requirements.	
Corrective		
Action Plan Reference	DNDC Table 4.2.2. Dags 2007 and 2.5.4 in Dags 2005	
Reference	BNBC- Table 4.3.2, Page-2887 and 3.5.1 in Page 2885	
Pictorial Evidence		



22	Do all stairways finish directly to outside or via a fire separated corridor?	NA
Section	Discharge Level	
Description	During the assessment, no stair was available in the factory. So this issue is not applicable.	
Corrective Action Plan		
Reference	BNBC-3.10.11 in Page 2898, 3.2 Page 2881	

23	Are evacuation routes protected from production areas and high risk uses all the way to outside?	6 Months
Section	Discharge Level	
Description	During the assessment, evacuation routes were not protected from high risk uses area (i.e. chemical stores found in the evacuation route).	
Corrective Action Plan	All high risk areas shall be fire separated by rated wall and rated door from the evacuation routes.	
Reference	BNBC- Table 3.2.1, Page- 2673 and 3.2.2 in Page 2882, Table 3.2.3 Page 2675	
Pictorial Evidence		



Fire Separation

24	Are any atria present linking more than two floors? If YES, are the upper floors fire separated from the atria?	NA
Section	Fire Separation	
Description	Atria was not avaiable during the assessment.	
Corrective Action Plan		
Reference	BNBC- 3.1.19.2(f), Page-2763 and 3.1.19.1 in Page 2762	

25	Are any vertical service shafts passing through two or more floors? If YES, are they provided with required fire resistance rating of walls/doors?	NA
Section	Fire Separation	
Description	Vertical service shafts were not available in the factory during the assessment.	
Corrective Action Plan		
Reference	BNBC- Table 3.3.1(a)	

26	Are any mezzanines present? If YES, are travel distances to a protected stairway or final exit within maximum allowable limits?	NA
Section	Fire Separation	
Description	During the assessment, mezzanines were not available in the factory.	
Corrective Action Plan		
Reference	BNBC- Table 4.3.4 and Table 4.3.8 and 1.14.6 in Page 2651	



27	Are all lifts provided with proper fire separation?	NA
Section	Fire Separation	
Description	There was no lift avaiable in the factory during the assessment.	
Corrective Action Plan		
Reference	BNBC- Table 3.3.1(a), 3.3.1 (b)	

28	Does the building have a Basement level? If YES, is it appropriately fire separated with an entry lobby, fire walls and fire rated self-closing doors?	NA
Section	Fire Separation	
Description	Basement level was not available in the factory during the assessment.	
Corrective Action Plan		
Reference	BNBC- 3.1.8, Page-2757 and BNBC-1.14.11.4 in Page 2652	



29	Are Permanent / Designated Storage areas (if adjacent to production area) separated with fire rated walls / doors?		6 Months
Section	Fire Separation		
Description	During the assessment, we found storage areas adjacent to productiom area without fire separation. Location: Production Shed.		
Corrective Action Plan	Storage area (Permanent / Designated) shall be fire separated from the production area by fire rated walls and fire rated doors.		
Reference	BNBC- Table 3.2.1 in Page 2673		
Pictorial Evidence			



30	Are all high-risk rooms fire separated from the rest of the operational areas? (Boiler Room, Generator Room, Substation Room, Chemical Room.)	6 Months
Section	Fire Separation	
Description	Chemical stores at Godown Shed-1, Godown Shed-2 and Godov found without fire separation.	vn Shed-3 were
Corrective Action Plan	Chemical stores shall be fire separated by rated wall and rated door as per code.	
Reference	BNBC- Table 3.2.1 in Page 2673 and 2.11.7 in Page 2684	
Pictorial Evidence		



31	Are any smoke & heat vents required at any atria or storage area?	6 Weeks
Section	Fire Separation	
Description	During the assesment, we found the following information: (i) Chemical store at Godown Shed-1, Godown Shed-2 & Godown Shed-3. Smoke and heat vents were not found at chemical stores and production areas.	
Corrective Action Plan	The factory shall install smoke & heat vent at chemical stores as	per code.
Reference	BNBC-2.6, Page- 2871 and Table 4.2.1	

32	Is there any opening or penetration in slab or wall? If YES, is it properly sealed with appropriate fire rating?	NA
Section	Fire Separation	
Description	During the assessment, opening or penetration in slab or wall was not found.	
Corrective Action Plan		
Reference	BNBC- Table 3.2.1 & Table 3.3.1(a), 3.3.1 (b) in Page 2673, 2749 2869	and 2.5 in Page



Safety Systems

33	Are all evacuation pathways appropriately sign posted?	1-2 Weeks
Section	Safety Systems	
Description	Aisle marking & exit signage are not provided in all floor operation exit doors in the entire factory.	onal areas as well as
Corrective Action Plan	Provide aisle marking with arrow guiding and exit signage on all Evacuation pathways or provided with overhead signage fixed at ceiling level. - Illuminated exit sign should be posted above the exit door, - It should be clearly visible at all time, - Provide directional signs wherever necessary. - All exit doors should be clearly marked for easy identification. - Signage should be uniform.	
Reference	BNBC- 3.16, Page-2902	
Pictorial Evidence		



34	Are all evacuation pathways appropriately illuminated with emergency lighting?	6 Weeks
Section	Safety Systems	
Description	Emergency lighting was not provided for all evacuation pathways. Location: Production Shed, Godown Shed-1, Godown Shed-2, Godown Shed-3, Office Building, etc.	
Corrective Action Plan	The factory shall install the emergency lights at evacuation pathways to ensure appropriate illumination as per code.	
Reference	BNBC- 1.2.7.2(a), Page-4539	

35	Are all evacuation stairways appropriately illuminated with emergency lighting?	NA
Section	Safety Systems	
Description	There was no stairway in the factory premises.	
Corrective		
Action Plan		
Reference	BNBC- 1.2.7.2(b), Page-4539	



36	Is the emergency lighting system provided with back-up power supply?	1-2 Weeks
Section	Safety Systems	
Description	Emergency lighting as well as back-up power supply was not provided for all evacuation pathways. Location: Production Shed, Godown Shed-1, Godown Shed-2, Godown Shed-3, Office Building, etc.	
Corrective Action Plan	The illumination of exit signs and the lighting of the means of escape and exit access shall be powered by an alternate or emergency electrical system to ensure continued illumination for a duration of not less than 30 minutes after the failure of primary power supply.	
Reference	BNBC-1.2.7.2(c), Page-4539	



37	Are detectors provided? Which types of detectors are provided?	6 Months
Section	Safety Systems	
Description	During the assessment, detectors were not provided in the factory. The factory production area hazard condition is chemical hazardous (Occupancy: J) and the area of the Production Shed is 1006 sft, so automatic detection and fire alarm system is required, but automatic fire detectors and alarm system were not provided in the entire factory.	
Corrective Action Plan	Prepare design drawings for the fire detection and alarm system in accordance with the code requirements and hazard situation, (with appropriate specifications and drawings) showing how they will be implemented along with an implementation plan. Install the fire detection and alarm systems in accordance with the code requirements (based on appropriate specifications and design/ drawings).	
Reference	BNBC- 4.6.1(b), Page- 2923, 5.12 Page 2939	
Pictorial Evidence		



38	Is there a manual or automatic fire detection and alarm system that complies with BNBC guidelines?	6 Months
Section	Safety Systems	
Description	Automatic detection & alarm system were not provided in the entire factory. The factory production area hazard condition is chemical hazardous (Occupancy: J) and the area of the Production Shed is 1006 sft = 93.46 sqm, so automatic detection and alarm system is required.	
Corrective Action Plan	Install an automatic fire alarm and detection systems in accordance with the code to fulfill the requirements.	
Reference	BNBC- PART IV, Appendix C in Page 2957	

39	Are the manual activation points appropriately spaced?	6 Weeks
Section	Safety Systems	
Description	The manual activation points were not installed. Location: All buildings & sheds.	
Corrective Action Plan	The manual activation call point should be installed at all exit routes of the building as per design.	
Reference	BNBC-1.3.37 (BS-5839), Page-4613	

40	Does the alarm system covers all floors?	6 Weeks
Section	Safety Systems	
Description	The factory did not install fire alarm system. Location: All buildings & sheds.	
Corrective Action Plan	An automatic alarm system shall be installed throughout the factory as per code.	
Reference	BNBC- 4.6.2.2, Page-2923	



41	Is the number of detectors sufficient for coverage of the production floors and stores as per Standard?	6 Weeks
Section	Safety Systems	
Description	The factory did not install an automatic fire detection and alarm floor area, floor height and hazard criteria (J) an automatic fire c system is required in the factory. Location: All buildings & sheds.	' '
Corrective Action Plan	The factory shall install fire detection and alarm system which covers the production floors and storage areas, etc. as per code.	
Reference	BNBC- PART IV, Appendix C in Page 2957	

42	Does the factory have provision of periodic checking of alarm call point, alarm & detection system with maintaining record properly?	1-2 Weeks
Section	Safety Systems	
Description	During the assessment, we did not find any alarm call point, alarm and detection system.	
Corrective Action Plan	The factory shall perform periodic checking of alarm call point, alarm & detection system with maintaining record properly after installing the system.	
Reference	BNBC- A.9.1, Page-2948	



43	Are the right numbers of extinguishers present & properly tagged?	1-2 Weeks
Section	Safety Systems	
Description	Right numbers of fire extinguishers were not present in the factory during the assessment. Total area: 460 square meters Total installed extinguisher: 4 Tagged with fill date and expire date were available, but manufactures instructions, checklist, refill data were not available in the factory during the assessment.	
Corrective Action Plan	The factory shall provide right number of fire extinguishers that meet the requirements of the code. Also, ensure regular monitoring and maintenance of extinguishers, including inspection and expiry/re-service labels/refill data. Ensure easy accessibility to fire extinguishers.	
Reference	Fire Service Rules, 2014; 13th Tofshil, Page- 18527, Labour rules 2015 Page 7340 - 55(2),(3),(4)	
Pictorial Evidence	JOHA DOMESTICATION OF THE PROPERTY OF THE PROP	Matter Acquiry Attenue DIA ENTERPRISE For Fight of Acquirement A processor that Acquirement

44	Are the extinguishers appropriately spaced?	1-2 Weeks
Section	Safety Systems	
Description	Fire extinguishers were not found at Godown Shed-3. Also, the spacing of fire extinguisher was not maintained properly in some of the areas (i.e. Production Shed, Godown Shed-1, Godown Shed-2, etc.).	
Corrective Action Plan	The factory shall install the extinguishers appropriately, and spaced as per the manufacturer's instructions which will provide the total coverage of the factory.	
Reference	BNBC-4.4, Fire Service Rules, 2014; 13th Tofshil, Page- 18527	



45	Does the factory have dedicated fire pump or hydrant system?	6 Months
Section	Safety Systems	
Description	Fire pump or hydrant system was not available in the factory.	
Corrective Action Plan	The factory shall take an initiative dedicated fire pump or hydrant system - Prepare, design, drawing of the fire pump system or hydrant system based on hazard criteria also hydraulic calculation of the system which meet the requirement and will be installed pump system follow NFPA-20 guideline as per code.	
Reference	BNBC- 5.9.2(o) & (p), Page -2937, 5.12 Page 2939 , 5.10 Page 29	938

46	Does the dedicated fire pump or hydrant system have alternative power backup?	6 Weeks
Section	Safety Systems	
Description	Fire pump or hydrant system was not available in the factory.	
Corrective Action Plan	The factory shall prepare design & drawing of the dedicated fire pump system with alternative power backup & shall be installed as per code.	
Reference	BNBC- 4.2.2.5, Page-2909	

47	Does the factory have provision of periodic checking of fire pump or hydrant system with maintaining record properly?	1-2 Weeks
Section	Safety Systems	
Description	Fire pump or hydrant system was not available in the factory.	
Corrective Action Plan	After completing installation of fire pump or hydrant system factory shall maintain a periodic checking and maintaining record properly.	
Reference	BNBC-4.2.12.3, Page- 2918	



48	Does the number of hose meet the requirement of code in all floors?	6 Months
Section	Safety Systems	
Description	The factory did not install the fire hose system in the factory premises.	
Corrective Action Plan	Irequired number of hose which meet the requirements of the code in all floor	
Reference	BNBC- 4.2.3, Page-2910	

49	Does the diameter of first aid hose and standpipe meet the requirement of code?	6 Weeks
Section	Safety Systems	
Description	During the assessment, we did not find first aid hose and standp the factory.	ipe system within
Corrective Action Plan	The factory shall ensure the hose connection to a standpipe for be at least 100 mm nominal and that of small stream may be 63 each point. The size of first aid hose shall be 38 mm nominal. Th not be more than 30 m.	mm or 50 mm on
Reference	BNBC- 4.2.3.11, Page-2913	

50	Is the performance of hose (water pressure) satisfactory?	6 Months
Section	Safety Systems	
Description	During the assessment, hose system was not available in the fac	tory.
Corrective Action Plan	Ishall be at least 300 kPa. For standpipe supplying first aid hose (38 mm nominal	
Reference	BNBC- 4.2.3.3, Page-2911	



51	Is the standpipe and first aid hose performance being checked periodically and tagged properly?	1-2 Weeks
Section	Safety Systems	
Description	Standpipe and hose system were not available in the factory.	
Corrective Action Plan	The factory shall maintain testing, inspection and maintenance documents of standpipe and first aid hose system periodically after installing the system.	
Reference	BNBC- 2.4.4.1, Page-2676 and 4.2.2.4 in Page 2908	

52	Does the factory have sufficient water capacity connected to hose to supply water during peak demand period?	6 Months
Section	Safety Systems	
Description	The factory did not have dedicated water reservoir sufficient capacity.	
Corrective Action Plan	Prepare plan and design for dedicated water storage tank & construct it which meets the peak demand period firefighting.	
Reference	BNBC- Table 4.4.1, Page-2905	

53	Is a fire-fighting lift provided in high rise (above 33m) buildings?	NA
Section	Safety Systems	
Description	There was no high rise building in the factory premises.	
Corrective		
Action Plan		
Reference	BNBC- 2.11, Page- 2876	



54	Are fire-fighting truck access roads wide enough and free of obstacles?	Compliant
Section	Safety Systems	
Description	Fire-fighting truck access roads were wide enough and free of ol	bstacles.
Corrective Action Plan		
Reference	BNBC- 1.7, Page-2633	
Pictorial Evidence		

55	Are fire-fighting additional equipment provided at the right location? Sand, water, buckets, etc.	Compliant
Section	Safety Systems	
Description	During the assessment, we found additional fire fighting equipn water, bucket, etc. in the factory premises.	nent like sand,
Corrective		
Action Plan		
Reference	Bangladesh Labour Rules, 2015, rules 55(1)	
Pictorial Evidence		



56	Is a Fire Command Station provided at Ground floor in high rise buildings?	NA
Section	Safety Systems	
Description	There was no high rise building in the factory premises.	
Corrective Action Plan		
Reference	BNBC- A.5.5,Page-2945	

57	Is/Are there P. A. (Public Address) system/s which is/are audible from all corner/s of factory?	6 Weeks
Section	Safety Systems	
Description	P.A. (Public Address) system was not available in the factory.	
Corrective Action Plan	I having communication to all floors as well as facilities to receive messages from all	
Reference	BNBC-3.15.2, Page-4746	



58	Are there combustible materials found near heat/ electrical source (near DB, SDB and electrical installations, loose electrical connection) in store or production floor?	1-2 Weeks
Section	Safety Systems	
Description	During the assessment, combustible materials were found near source. Location: Production Shed.	the electrical
Corrective Action Plan	The factory shall remove all the flammable material in front of the electrical circuitry of distribution panels.	
Reference	Best Practice	
Pictorial Evidence		

59	Is there back-up power supply provided for the alarm system? Battery, IPS, etc.	6 Weeks
Section	Safety Systems	
Description	The factory did not install fire alarm and detection system yet.	
Corrective Action Plan	The factory shall provide back-up power supply for a control par detection system after installing the system.	nel of fire alarm and
Reference	Best Practice	



60	Is the visual alarm placed in working condition where required?	NA
Section	Safety Systems	
Description	During the assessment, we did not find any occupying area where the ambient noise above 90 dBA. So, visual alarm is not require as per present conditions.	
Corrective Action Plan		
Reference	BNBC-1.3.37, Page- 4613 and 4.6.2.1(b) in Page 2923	

Management

61	Does the factory have the valid Fire License/ permit?		Compliant
Section	Management		
Description	During the assessment, Fire license was available and up to date in the factory.		
Corrective			
Action Plan			
Reference	Best Practices		
Pictorial Evidence	1 100	(a) পাই পাইলেক মন্ত্ৰাপতিয়ানা নামে এবং তেলপানতে ভিন্নত হ'ব (b) পাইলোকৰ সম্ভাৱনী মধ্যমনভাৱে শালিত এইতেমে বিনা ভাষ	ম ত চ ত ত ত ত ত ত ত ত ত ত ত ত ত ত ত ত ত



62	Does the factory building approval from authority? 6 Weeks		
Section	Management		
Description	During assesment, we found the following information from the factory: (i) Building approval drawing was not available from the local authority. (ii) Building layout plan was approved from DIEF.		
Corrective Action Plan	The factory shall prepare update layout plan and take approval from local authority.		
Reference	Best Practices		
Pictorial Evidence	FRONT ELEVATION (S	SOUTH) पादक मेर २६ ७० (जिल्लाह मेर १९ ग्री १०) जना त्यामिक (जार पारक मेर १० वर्ष केर)	



63	Are all production units/ floors covered in fire license?	Compliant
Section	Management	
Description	During the assessment, fire lisence was available & updated at the name of factory address but no floor area mentioned.	
Corrective Action Plan		
Reference	Best Practices	
Pictorial Evidence	(5) make (6) make (7)	ম

64	Does the factory have single fire safety management system in case of multi tenancy?	NA
Section	Management	
Description	There was no multi tenancy in the factory.	
Corrective		
Action Plan		
Reference	Best Practices	



65	Does the factory have boiler license?	NA
Section	Management	
Description	During the assessment, Boiler was not available in the factory.	
Corrective Action Plan		
Reference	Best Practices	

66	Does the factory have boiler operator license?	NA
Section	Management	
Description	During the assessment, Boiler was not available in the factory. So boiler operator license is not applicable.	
Corrective		
Action Plan		
Reference	Best Practices	

67	Does the factory conduct fire drill regularly covering all shifts maintaining record properly?	1-2 Weeks
Section	Management	
Description	During the assessment, factory authority did not show any documents about fire drill and maintaining records.	
Corrective Action Plan	Fire drill shall be conducted as detailed under the fire safety plan. The frequency of fire drill shall be as per BNBC Table 4.A.1. All occupants of the buildings, building service employees including fire safety and evacuation plan staff shall participate in the fire drill. A record of such drills shall be kept in writing for at least 3 years for the inspection Department of Fire Service and Civil Defence whenever called for.	
Reference	BNBC-Table 4.A.1 in Page 2947	



DIFE Summary

Name of Factory	Manila Chemical Company
Address of Factory	2-no Jungle Latifpur, Jafrabad, Shitakundo, Chattogram.
Present Status	Under Operation
Fire Assessment conducted by	Aipro Engineering and Consultancy Service
Date of Inspection	27 th & 28 th February, 2021

Recommendations for Corrective Action

Immediate:

No corrective actions

Short Term (1-2 Weeks):

- The factory shall maintain the minimum width of passageways, corridor 1.12 m for industrial area (Occupancy: G1, G2) and 0.915 m for storage area, high hazardous area (Occupancy: H1, H2, J) at the evacuation pathways as per code.
- The factory will remove all temporary stored items from evacuation pathways & ensure all evacuation pathways shall be free from temporary stored item.
- Provide aisle marking with arrow guiding and exit signage on all Evacuation pathways or provided with overhead signage fixed at ceiling level.
- Illuminated exit sign should be posted above the exit door,
- It should be clearly visible at all time,
- - Provide directional signs wherever necessary.
- All exit doors should be clearly marked for easy identification.
- Signage should be uniform.
- The illumination of exit signs and the lighting of the means of escape and exit
 access shall be powered by an alternate or emergency electrical system to
 ensure continued illumination for a duration of not less than 30 minutes after
 the failure of primary power supply.
- The factory shall perform periodic checking of alarm call point, alarm & detection system after installation with maintaining record properly.
- Provide right number of fire extinguishers that meet the requirements of the code. Ensure regular monitoring and maintenance of extinguishers, including inspection and expiry/re-service labels/refill data. Ensure easy accessibility to fire extinguishers.



- The factory shall install the extinguishers appropriately, and spaced as per the manufactures instructions which will provide the total coverage of the factory.
- After completing installation of fire pump or hydrant system factory shall maintain a periodic checking and maintaining record properly.
- The factory shall maintain testing, inspection and maintenance documents of standpipe and first aid hose system periodically after installing the system.
- The factory shall remove all the combustible material in front of the electrical circuitry of distribution panels.
- Fire drill shall be conducted as detailed under the fire safety plan. The frequency
 of fire drill shall be as per BNBC Table 4.A.1. All occupants of the buildings,
 building service employees including fire safety and evacuation plan staff shall
 participate in the fire drill. A record of such drills shall be kept in writing for at
 least 3 years for the inspection Department of Fire Service and Civil Defence
 whenever called for.

Mid Term (6 Weeks):

- The factory shall ensure to replace existing exit doors on evacuation routes, exit doors with side hinged type door, which swing outward and in the direction of travel.
- Remove all locking device from all egress doors. All exit doors should be openable from the side they serve without the use of a key.
- Factory shall ensure the emergency exits minimum 1 meter per exit as per code.
- The factory shall install smoke & heat vent at chemical stores and production areas as per code.
- The factory shall install the emergency lights at evacuation pathways to ensure appropriate illumination as per code.
- The manual activation call point should be installed at all exit routes of the building as per design.
- An automatic alarm system shall be installed throughout the factory as per code.
- The factory shall install fire detection and alarm system which covers the production floors and storage areas, etc. as per code.
- The factory shall prepare design & drawing of the dedicated fire pump system with alternative power backup & shall be installed as per code.
- The factory shall ensure the hose connection to a standpipe for large stream shall be at least 100 mm nominal and that of small stream may be 63 mm or 50 mm on each point. The size of first aid hose shall be 38 mm nominal. The hose length shall not be more than 30 m.
- The factory shall prepare design for P. A. (public address) system such a way that is having communication to all floors as well as facilities to receive messages from all floors also install the system which meets the requirement of the code.
- The factory shall provide back-up power supply for a control panel of fire alarm and detection system after installing the system.



 The factory shall prepare update layout plan and take approval from local authority.

•

Long Term (6 Months):

- The factory shall ensure the sum of the width of emergency exits Office Building (Minimum 1m per exit) as per code.
- All high risk areas shall be fire separated by rated wall and rated door from the evacuation routes.
- Storage area (Permanent / Designated) shall be fire separated from the production area by fire rated walls and fire rated doors.
- Chemical stores shall be fire separated by rated wall and rated door as per code.
- Prepare design drawings for the fire detection and alarm system in accordance with the code requirements and hazard situation, (with appropriate specifications and drawings) showing how they will be implemented along with an implementation plan. Install the fire detection and alarm systems in accordance with the code requirements (based on appropriate specifications and design/ drawings).
- Install an automatic fire alarm and detection systems in accordance with the code to fulfill the requirements.
- The factory shall take an initiative dedicated fire pump or hydrant system -Prepare, design, drawing of the fire pump system or hydrant system based on hazard criteria also hydraulic calculation of the system which meet the requirement and will be installed pump system follow NFPA-20 guideline as per code.
- The factory shall prepare proper design and plan also demonstrate it. Install required number of hose which meet the requirements of the code in all floor areas.
- Prepare a proper design and plan for the Standpipe and hose system. The factory shall install standpipe & hose system which will comply with the code requirements for supply of water with required pressure at top most hose connections.
- Prepare plan and design for dedicated water storage tank & construct it which meets the peak demand period firefighting.



Disclaimer

This report is intended to serve the Company in helping to understand the current safety conditions under the prevailing system and proposed changes that will help improve the safety and reliability of the systems installed at the Company's facility. At the time of the audit/ survey, all the systems were working as intended, as produced by the Company to the auditors. The above result reflects AIPRO Engineering & Consultancy Service's findings at the time and place of inspection.

This report does not release the Company or any other entity dealing with it from their contractual responsibilities nor does it prejudice any one's right of claim for compensation for any apparent and/ or hidden defects not detected during inspection or occurring anytime thereafter. This report indicates the measures advised to be installed at the facility to improve safety performance, provided that the compliance to the national standards and all legal and statutory requirements are adhered to by the Company. AIPRO Engineering & Consultancy Service doesn't hold the accountability or responsibility, directly or indirectly of any mishap/disaster happening in the facility audited as it doesn't have any control over the Company's process and practices. This report is made solely to the management of the Company for which this report is produced, as a body, in accordance with agreed scope of work and for no other purpose. AIPRO Engineering & Consultancy Service does not assume any responsibility to any other person or body for the content of this report.

AIPRO Engineering & Consultancy Service makes no representation or warrantee, either expresses or implied, with respect to this audit/ survey report, its quality, accuracy, or fitness for any specific application. Therefore, AIPRO Engineering & Consultancy Service shall have no liability to the company for which this report is produced, or any other person or entity with respect to any loss, liability or damage caused or alleged to have been caused directly or indirectly by the report. This includes, but not limited to, interruption of services, operations, losses of anticipatory profits or consequential damages from use of this report.

In so far as audit reports are prepared in the course of processing the order and which are subject to the protection of copyright, AIPRO Engineering & Consultancy Service shall grant the Company a simple, non-transferable right to use the audit report, insofar as this is necessary and in accordance with the contractually presupposed purpose. Other rights shall not be transferred; in particular, the Company shall not be entitled to modify (edit) audit/ survey reports or to make use of such reports outside of its business premises.

AIPRO Engineering & Consultancy Service, its staff and any experts that may be called in shall not disclose and use trade and business matters of the Company about which they have gained knowledge of during the performance of their work, without proper authorization.