

গণপ্রজাতন্ত্রী বাংলাদেশ সরকার শ্রম ও কর্মসংস্থান মন্ত্রণালয়

শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোতন কর্মপরিবেশ; াড়ে জুলবে স্মার্ট বাংলাদেশ"

ক্যাপ পর্ববেষ্ফণের তখ্য

কারখানার নাম	টিবিএইচ ফ্যাশন টেক্স
ঠিকানা	Kha-10/A, Bepari Para,
কারখানার কোড	DHK 581
কালার কোড	

মূল্যামনের ধরণ: কাঠামোগত মূল্যামন	পর্যবেষ্ফণের তারিখ: ০২–০২–২০২৩
১. পর্যবেষ্ফণ	

পরিদর্শন পর্ববেষ্ণণ	As-built Drawings
ক্যাপ	
আইটেম	
ক্যাটাগরি	

১.১. কাৰ্যক্ৰম

built Architechtural and structural drawings of the different structural elements,
indation detais to be prepared for the building. As part of this process building gineer will be required to make a number of checks on the as–built construction.
built drawings will be prepared by the Engineer.
ाजा नय
-%
-07-7940
ত হ্র্যুনি
01.2021: As- built architectural and structural drawing has been submitted to EE by "Bureau Veritus" but this is not acceptable now in DIFE. 01.09.2021: As- It architectural and structural drawing has been submitted to DIFE by "Bureau ritus" but this is not acceptable now in DIFE. They are advised to submit its all awings through DIFE enlisted consultancy firm. 03/08/2022: DEA report luding all as built designs and drawings must be resubmitted to DIFE as soon as assible. 02-02-2023: DEA report including all as built designs and drawings must resubmitted to DIFE as soon as possible.

সংখুক্তিসমূহ (৮)





4 TENE COMOS TRANSPORTATION

......



২. পর্যবেষ্ণণ

পরিদর্শন পর্শবেষ্ফণ	Distress in Primary Structural Element
ক্যাপ আইস্ট্রেয়	
ক্যাটাগরি ক্যাটাগরি	

২.১. কাৰ্শক্ৰম

কাৰ্যক্ৰম	The owner or user of the building should be vigilant about development of any distress, particularly in primary structural element such as columns. If crack appear, propagate and widen, detail assessment and adoption of the remedial measures may become necessary.
সুপারিশের তথ্যসূত্র	
কার্থানার কার্যক্রম	
<u>অগ্রা</u> ধিকার	অবিলয়ে
চুডান্ত সমশ্বসীমা	_
সংশোধিত সমশ্রসীমা	07-07-7940
অগ্রগতির অবস্থা	সংশোধিত
মন্তব্য	17.01.2021: No cracks is found in primary structural elements such as columns and slabs by visually during the inspection. 01.09.2021: No cracks is found in primary structural elements such as columns and slabs by visually during the inspection. 03/08/2022: No distress were found in any primary structural elements during the inspection date. 02-02-2023: No distress were found in any primary structural elements during the inspection date.

সংখুক্তিসমূহ (৪)







