

## গণপ্রজাতন্ত্রী বাংলাদেশ সরকার শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"শ্রমজীবী মানুষের অধিকার, বৈৰম্যাহীন বাংলাদেশের অঙ্গীকার"

# ক্যাপ পর্ববেষ্ফণের তথ্য

কারখানার নাম	ক্যাপম ক্যাশন লিঃ
ঠিকানা	Mouchak, Kaliakoir, Gazipur,
কারখানার কোড	<b>GZP</b> 177
কালার কোড	

মূল্যায়নের ধরণ: কাঠামোগত মূল্যায়ন	পর্ববেষ্ফণের তারিখ: 🕒
১. পর্ববেষ্ণণ	

পরিদর্শন পর্ববেষ্ফ	Lateral load carrying system of the building (North side extension portion) is not logical. 3 diameter steel pipe is used as columns. There are no vertical and horizontal bracing in-between pipes.	
ক্যাপ আইটেম ক্যাটাগরি		

১.১. কাৰ্যক্ৰম	
কাৰ্যক্ৰম	Provide calculations showing the structural adequacy of all columns, taking into account the loading plans and as built structure.
সুপারিশের তথ্যসূত্র	
	[Whom is going to carry out the recommendation?] [How will the recommendation be carried out?]
	প্রযোগ্য নর
চুড়ান্ত সময়সীমা	07-07-7240
সংশোধিত সময়সীমা	07-07-7240
অগ্রগতির অবস্থা	চলমাল
মন্তব্য	CVV1: 12–Feb–2020 Factory management has engaged a consultant and ensure consultant will submit document as soon as possible. But presently no test reports and work order have been found in the site during inspection. CVV2: 13–Nov–2019 Field work of DEA has been done but report is not yet submitted to DIFE. CVV3: 16–Mar–2020 An agreement on dated 27.09.2018 in between factory and consultant has been found. Core test report & evidence of core cutting location have been observed at site. Which is a part of DEA but DEA report & as built drawings are not yet submitted to DIFE. 12.October 2020:An agreement found made on 27.09.2018 in between factory and consultant. Core test report & evidence of core cutting location have been observed at site. Which is a part of DEA but DEA report & as built drawings are not yet submitted to DIFE. No bracing has provided during this time period. On 26–08–2021 :An agreement found made on 27.09.2018 in between factory and consultant. Core test report & evidence of core cutting location have been observed at site. Which is a part of DEA but DEA report & as built drawings are not yet submitted to DIFE. No bracing has provided during this time period.

#### ১.২. কাৰ্যক্ৰম কাৰ্যক্ৰম Building engineer to produce accurate and complete as-built documentation. সুপারিশের ভ৾খ্যসূত্র কারখানার কাৰ্যক্ৰম <u>অগ্রা</u>খিকার চুড়ান্ড *স*মশ্বসীমা সংশোধিত 07-07-2290 সময়সীমা <u>অগ্রগতির</u> চলমান <u>অবস্থা</u> CVV1: 12-Feb-2020 Factory management has engaged a consultant and ensure consultant will submit document as soon as possible. But presently no test reports and work order have been found in the site during inspection. CVV2: 13-Nov-2019 Field work of DEA has been done but report is not yet submitted to DIFE. CVV3: 16-Mar-2020 An agreement on dated 27.09.2018 in between factory and consultant has been found. Core test report & evidence of core cutting location have been observed at site. Which is a part of DEA but DEA report & as built drawings are not yet submitted to DIFE. 12.October 2020:An agreement found made on 27.09.2018 in মন্তব্য between factory and consultant. Core test report & evidence of core cutting location have been observed at site. Which is a part of DEA but DEA report & as built drawings are not yet submitted to DIFE. No bracing has provided during this time period. 26-08-2021 :An agreement found made on 27.09.2018 in between factory and consultant. Core test report & evidence of core cutting location have been observed at site. Which is a part of DEA but DEA report & as built drawings are not yet submitted to DIFE. No bracing has provided during this time period.

২. পর্ববেষ্ণণ

পরিদর্শন পর্ববেষ্ডণ	Approval drawing and structural design drawing have not been found.
ক্যাপ	
আইটেম	
ক্যাটাগরি	

### ২.১. কাৰ্যক্ৰম

	'
কাৰ্যক্ৰম	Engage a qualified structural engineer to prepare structural drawing, as built drawing and manage approval from concern authority.
সুপারিশের তথ্যসূত্র	
কারখীনার কার্বক্রম	
অগ্রাধিকার	প্রযোগ্য নয়
চুডান্ড সমশ্বসীমা	
সংশোধিত সময়সীমা	07-07-7940
অগ্রগতির অবস্থা	চলমান
<b>মন্ত</b> ব্য	CVV1: 12–Feb–2020 Factory management has engaged a consultant and ensure consultant will submit document as soon as possible. But presently no test reports and work order have been foun in the site during inspection. CVV2: 13–Nov–2019 Field work of DEA has been done but report is no yet submitted to DIFE. CVV3: 16–Mar–2020 An agreement on dated 27.09.2018 in between factory and consultant has been found. Core test report & evidence of core cutting location have been observed at site. Which is a part of DEA but DEA report & as built drawings are not yet submitted to DIFE. A new shed has been found in south side, which was merge with main production shed. A submission letter on dated 01.01.2020 to upazilla Engineer, Kaliakoir, Gazipur about Building Approval Plan has been found on site. 12.October 2020:An agreement found made on 27.09.2018 in between factory and consultant. Core test report & evidence of core cutting location have been observed at site. Which is a part of DEA but DEA report & as built drawings are not yet submitted to DIFE. A new shed has been found in south side, which was merge with main production shed. A submission letter on dated 01.01.2020 to upazilla Engineer, Kaliakoir, Gazipur about Building Approval Plan has been found on site. 26–08–2021 :An agreement found made on 27.09.2018 in between factory and consultant. Core test report & evidence of core cutting location have been observed at site. Which is a part of DEA but DEA report & as built drawings are not yet submitted to DIFE.

#### ২.২. কাৰ্যক্ৰম

	Prepare calculations showing the structural adequacy of the building structure taking into account
	the factory design imposed loading and the as built structure.
সুপারিশের	
ভখ্যসূত্র	
কার্খানার	
কাৰ্যক্ৰম	
অগ্রাধিকার	
চুডান্ত	
<i>ने</i> भग्ननीभा	
সংশোধিত	0/-0/-/940
সময়সীমা	0 9 - 0 9 - 9 9 d 0
অগ্রগতির	
অবস্থা	চলমান
<b>মন্ত</b> ব্য	CVV1: 12–Feb–2020 Factory management has engaged a consultant and ensure consultant will submit document as soon as possible. But presently no test reports and work order have been foun in the site during inspection. CVV2: 13–Nov–2019 Field work of DEA has been done but report is not yet submitted to DIFE. CVV3: 16–Mar–2020 An agreement on dated 27.09.2018 in between factory and consultant has been found. Core test report & evidence of core cutting location have been observed at site. Which is a part of DEA but DEA report & as built drawings are not yet submitted to DIFE. 12.October 2020:An agreement found made on 27.09.2018 in between factory and consultant Core test report & evidence of core cutting location have been observed at site. Which is a part of DEA but DEA report & as built drawings are not yet submitted to DIFE 26–08–2021:An agreement found made on 27.09.2018 in between factory and consultant. Core test report & evidence of core cutting location have been observed at site. Which is a part of DEA but DEA report & as built

# 

কাৰ্যক্ৰম	Demolish the wall. Otherwise, carry out repairing and remedial actions as directed by the Building Engineer for these cracks.
সুপারিশের	
<u>তথ্যসূত্র</u>	
কার্খানার	
<u>কাৰ্যক্ৰম</u>	
<u> অগ্রাখিকার</u>	অবিলয়ে
চুডান্ত সময়সীমা	-
সংশোধিত সময়সীমা	07-07-7940
অগ্রগতির অবস্থা	সংশোধিত
<b>মন্ত</b> ব্য	12.October 2020:At the time of inspection no crack obsrved on that wall. They chipped through the wall, plastered there and then painted the wall. 26–08–2021:At the time of inspection no crack obsrved on that wall. They chipped through the wall, plastered there and then painted the wall.