

গণপ্রজাতন্ত্রী বাংলাদেশ সরকার শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোতন কর্মপরিবেশ; গড়ে জুলবে স্মার্ট বাংলাদেশ"

ক্যাপ পর্ববেষ্ফণের তথ্য

কারখানার নাম	অনন্ত স্পোর্টস ওব্যাব লিঃ
ঠিকানা	Nishchintapur, Savar, Dhaka
কারখানার কোড	DHK045
কালার কোড	

	া: কাঠামোগত মুল্যান্থন পর্ববেষ্ণণের তারিখ: ২৭–০৮–২০২		
. পর্ববেষ্ <u>ষণ</u> পিরিদর্শন			
পর্ববেষ্কণ			
ক্যাপ আইটেম			
ক্যাটাগরি			
১.১. কাৰ্যক্ৰঃ	7		
কার্যক্রম সুপারিশের তথ্যসূত্র	Building engineer to draw up plans for water proofing and drainage for the roof.		
কার্থানার কার্বক্রম	we have taken action and completed this issue.		
I 	ৰ প্ৰযোগ্য লয়		
চুডান্ড সম্যুসীমা	_		
সংশোধিত সমশ্রসীমা			
অগ্রগতির অবস্থা	সংশোধিত		
মন্তব্য	CVV Date- 27/12/2020: The factory has been completed its roof water proofing with proper rain water drainage system. On 07/06/2021:Remedial action has been taken regarding this issue. On 26.08.2021: Roof water proofing with proper rain water drainage system has completed 27/08/2022: Proper water proofing and drainage system was found during inspection date.		
সংযুক্তি	সংসুক্তিসমূহ (২)		

পরিদর্শন পর্শবেষ্ <u>ড</u> ণ	No proper roof drainage and water proofing
ক্যাপ	
আখড়েশ ক্যাটাগরি	

	<u></u>
কাৰ্শক্ৰম	Install water proofing and drainage system.
সুপারিশের	
ভ৾খ্যসূত্ৰ	
কার্খানার	We have taken action and completed this issue.
কাৰ্যক্ৰম	We have taken action and completed this issue.
<u>অগ্রা</u> ধিকার	প্রশোজ্য নয়
চুডান্ত	
সময়সীমা	
সংশোধিত	02-02-229
সমশ্রসীমা	
<u>অগ্রগতির</u>	সংশোধিত
অবস্থা	
মন্তব্য	CVV Date- 27/12/2020: The factory has been completed its roof water proofing with proper rain water drainage system. On 07/06/2021:Remedial action has been taken regarding this issue. On 26.08.2021: Roof water proofing with proper rain water drainage system has completed 27/08/2022: Proper water proofing and drainage system was found during inspection date.

সংখুক্তিসমূহ (২)





পরিদর্শন পর্শবেষ্ডণ	Exposed reinforcement
ক্যাপ আইটেম	
নাহতেন ক্যাটাগরি	

suggest a
nforcement is action has been is no exposed 022: No Exposed
a

সংযুক্তিসমূহ (२)





পরিদর্শন পর্শবেষ্ <u>ড</u> ণ	Exposed reinforcement
ক্যাপ	
আখ্ডেশ ক্যাটাগরি	

কাৰ্যক্ৰম	Carry out any remedial actions as directed by the Building Engineer.
সুপারিশের	
তথ্যসূত্র	
কার্খানার	We have taken action and completed this issue.
কাৰ্যক্ৰম	·
অগ্রাধিকার	প্রযোগ্য নয়
চুডান্ত	_
সময়সীমা	
সংশোধিত	02-02-2590
সময়সীমা	- a - a att -
<u>অগ্রগতির</u>	সংশোধিত
অবস্থা	
	CVV Date- 27/12/2020: During the visit, There is no exposed reinforcement is
	found on the roof floor of the building. On 07/06/2021:Remedial action has been
মন্ত ব্য	taken regarding this issue. On 26.08.2021: During the visit, There is no exposed
	reinforcement is found on the roof floor of the building. 27/08/2022: No Exposed
	reinforcements were found during inspection date.

সংশুক্তিসমূহ (২)






পরিদর্শন পর্ববেষ্ফণ	Sheds do not appear on drawings
ক্যাপ আইটেম ক্যাইখনি	

V. 00. 11 17-1		
<u> </u>	Building to prepare as built drawings. Drawings to be submitted to authorities for	
কাৰ্যক্ৰম	approval.	
সুপারিশের তখ্যসূত্র		
কার্খানার কার্শক্রম	We will engage a building engineer to prepare as built drawings. Drawings will be submitted to authorities for approval.	
<u>অগ্রা</u> খিকার	প্রযোগ্য নয়	
চুডান্ড সময়সীমা	ob-ob-2o59	
সংশোধিত সময়সীমা	07-07-7940	
অগ্রগতির অবস্থা	সংশোধিত	
মন্তব্য	CVV Date- 27/12/2020: As-built drawings have been prepared through DIFE non-listed consultancy firm. So the factory is advised to submit its drawings and analysis to DIFE through DIFE enlisted consultancy firm. On 07/06/2021: The drawing of Sheds is appear on as built architectural drawing and its specification found on structural drawing. On 26.08.2021: The drawing of Sheds is appear on as built architectural drawing and its specification found on structural drawing. 27/08/2022: Sheds were appear on as built architectural drawing and its specification found on structural drawing during inspection date.	
সংযক্তিসমূহ (১)		

সংশুক্তিসমূহ (১)



পরিদর্শন পর্ববেষ্ণণ	Non engineered connection and bracing system
ক্যাপ্	
আই(টেম্	
ক্যাটাগরি	

কাৰ্যক্ৰম	The connection of steel structure needs to be checked by building engineer and the bracing system is required to ensure the stability of the structure.
সুপারিশের	
জুখ্যসূত্র ভিখ্যসূত্র	
	We will engage a building engineer to obseve the connection of steel structure to
কাৰ্যক্ৰম	check the bracing system to ensure the stability of the structure.
	প্রযোগ্য নর
চুডান্ত সময়সীমা	ob-ob-2029
সংশোধিত সমশ্বসীমা	02-02-229
অগ্রগতির অবস্থা	সংশোধিত
মন্তব্য	CVV Date- 27/12/2020: The connection of steel structure have been checked through DIFE non-listed consultancy firm. So the factory is advised to submit its drawings and analysis to DIFE through DIFE enlisted consultancy firm. On 07/06/2021: The connection of steel structure have been checked through consultancy firm. Non engineering connection and bracing system has not been found on roof. Retrofitting drawing of roof shed was found on site and the factory management has already exicute the remidiation process of roof truss. On 26.08.2021: The connection of steel structure have been checked through consultancy firm. Non engineering connection and bracing system has not been found on roof. Retrofitting drawing of roof shed was found on site and the factory management has already exicute the remidiation process of roof truss. 27/08/2022: The DEA report has received approval from RSC. As Built drawing and retrofit drawing were found on site during inspection date.

সংখুক্তিসমূহ (২)





পরিদর্শন পর্ববেষ্ফণ	Non engineered connection and bracing system
ক্যাপ	
<u>আইটেম</u>	
ক্যাটাগরি	

ा.च. मा भिना		
কাৰ্যক্ৰম	Carry out any remedial actions as directed by the Building Engineer.	
সুপারিশের তখ্যসূত্র		
কারখানার কার্বক্রম	remedial actions as directed by the Building Engineer.	
অগ্রাধিকার	প্রবোজ্য নয়	
চুডান্ড সমশ্রসীমা	ob-2o-2o39	
সংশোধিত সমশ্রসীমা	07-07-7940	
অগ্রগতির অবস্থা	সংশোধিত	
মন্তব্য	CVV Date – 27/12/2020: The remedial action has been completed by Building Engineer but the consultancy firm is DIFE non–listed. So the factory is advised to submit its drawings and analysis to DIFE through DIFE enlisted consultancy firm. On 07/06/2021:The connection of steel structure have been checked through consultancy firm.Non engineering connection and bracing system has not been found on roof. Retrofitting drawing of roof shed was found on site and the factory management has already exicute the remidiation process of roof truss. On 26.08.2021: The connection of steel structure have been checked through consultancy firm.Non engineering connection and bracing system has not been found on roof.Retrofitting drawing of roof shed was found on site and the factory management has already exicute the remidiation process of roof truss. On 26.08.2021: The connection of steel structure have been checked through consultancy firm.Non engineering connection and bracing system has not been found on roof.Retrofitting drawing of roof shed was found on site and the factory management has already exicute the remidiation process of roof truss. 27/08/2022: The DEA report has received approval from RSC. As Built drawing and retrofit drawing were found on site during inspection date.	

সংযুক্তিসমূহ (২)



