

গণপ্রজাতন্ত্রী বাংলাদেশ সরকার শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"শ্রমজীবী মানুষের অধিকার, বৈৰম্যাহীন বাংলাদেশের অঙ্গীকার"

ক্যাপ পর্ববেষ্ফণের তথ্য

কারখানার নাম	ছোসেইনস লিমিটেড।
ঠিকানা	Plot # 103, Dhaka Mymensingh Road, Sector # 7, Uttara C/A, Uttara, DHAKA
কারখানার কোড	DHK258
কালার কোড	

মুল্যায়নের ধরণ: কাঠামোগত মুল্যায়ন	পর্ববেষ্ফণের তারিখ: –
১. পর্যবেষ্ট্রণ	

পিরিদর্শন	
পর্যবেক্স	Moderate overstress has been found in corner, edge column, central column
11(1-4	
ক্যাপ	
অাইনেম	
11200	2
 \$\ 6 5 4	1

১.১. কাৰ্শক্ৰ	
কাৰ্শক্ৰম	Qualified structural Engineer to be reviewed design, loads and columns stresses in the area identified above.
সুপারিশের	
ভখ্যসূত্র	
কার্থানার কার্বক্রম	[Whom is going to carry out the recommendation?] [How will the recommendation be carried out?]
অগ্রাধিকার	৬ মপ্তাহ
চুডান্ড সমশ্বসীমা	07-07-7940
সংশোধিত সময়সীমা	07-07-7940
অগ্রগতির অবস্থা	শুক হ্বলি
মন্তব্য	24.08.20 Visit observation: The factory management did not agreement with any enlisted consultnt firm. This is 15 storied building and the factory located in 13th floor,14th floor and roof top. Shade portion is located in roof top. The operational work in on going in these floors. 18/11/2020 Visit Observation: This issue covered under DEA. Not started anything regarding this issue. No agreement done with any DIFE enlisted consulting firm to do the structural design & drawings. Now the factory management is instructed to do all structural design & drawings along with DEA by an enlisted firm of DIFE and submit them to DIFE RCC within 31/12/2020. 25/08/2021 Visit Observation: Same as previous. This issue covered under DEA. Not started anything regarding this issue. No agreement done with any DIFE enlisted consulting firm to do the structural design & drawings. Now the factory management is instructed to do all structural design & drawings along with DEA by an enlisted firm of DIFE and submit them to DIFE RCC within 25/09/2021.

১.২. কার্যক্রম			
	Verify in situ concrete stresses either by 100mm dia. cores or existing cylinder strength data for [the identified columns]		
কাৰ্যক্ৰম	or [100mm dia. cores from 4 columns].		
সুপারিশে	न		
ভ৾খ্যসূত্র			
কার্খানা	티		
কাৰ্শক্ৰম অগ্ৰাধিক			
	, s		
চুডান্ড সময়সীম	_T -		
সংশোধি	5		
সমশ্রসীম			
অগ্রগতির অবস্থা	শুক হয়নি		
মন্তব্য	24.08.20 Visit observation: No step is taken regarding this issue by the factory. 18/11/2020 Visit Observation: This issue covered under DEA. Not started anything regarding this issue. No agreement done with any DIFE enlisted consulting firm to do the structural design & drawings. Now the factory management is instructed to do all structural design & drawings along with DEA by an enlisted firm of DIFE and submit them to DIFE RCC within 31/12/2020. 25/08/2021 Visit Observation: Same as previous. This issue covered under DEA. Not started anything regarding this issue. No agreement done with any DIFE enlisted consulting firm to do the structural design & drawings. Now the factory management is instructed to do all structural design & drawings along with DEA by an enlisted firm of DIFE and submit them to DIFE RCC within 25/09/2021.		

১.৩. কাৰ্বক্ৰম		
কাৰ্যক্ৰম	Produce and actively manage a loading plan for all floor plates within the factory giving consideration to floor capacity and column capacity.	
সুপারিশের ভখ্যসূত্র		
কারখানার কার্যক্রম		
<u>অগ্রা</u> ধিকার		
চুডান্ড সমশ্রসীমা	-	
সংশোধিত সমশ্বসীমা	07-07-7930	
অগ্রগতির অবস্থা	শুৰু হ্ৰ্যনি	
মন্ত ব্য	24.08.20 Visit observation: The factory management did not agreement with any enlisted consultant firm. 18/11/2020 Visit Observation: This issue covered under DEA. Not started anything regarding this issue. No agreement done with any DIFE enlisted consulting firm to do the structural design & drawings. Now the factory management is instructed to do all structural design & drawings along with DEA and vetted load plan by an enlisted firm of DIFE and submit them to DIFE RCC within 31/12/2020. 25/08/2021 Visit Observation: Same as previous. This issue covered under DEA. Not started anything regarding this issue. No agreement done with any DIFE enlisted consulting firm to do the structural design & drawings. Now the factory management is instructed to do all structural design & drawings along with DEA by an enlisted firm of DIFE and submit them to DIFE RCC within 25/09/2021.	

২. পর্যবেষ্ণণ

পরিদর্শন	There is an undocumented pre-engineered building shed covering around 50% area and RCC
পর্ববেষ্ণণ	structure covering 30% area over roof top (marked in roof plan).
ক্যাপ	
<u>আইটেম</u>	
ক্যাটাগরি	

২.১. কার্যক্রম Carry out any upgrade measures required as part of the design checks. Building Engineer কাৰ্যক্ৰম to carry out design checks on additional structure in particular resistance to wind uplift and loads from roof columns which are off grid. |সুপারিশের ভখ্যসূত্ৰ |কারখানার কাৰ্যক্ৰম **অগ্রাধিকার** ৬ সপ্তাহ চডান্ত *স*মশ্রসীমা সংশোধিত 02-02-2290 সময়সীমা অগ্রগতির শুরু হয়নি অবস্থা 24.08.20 Visit observation: We have found the same situation in the roof top which is covering shed around 50% area and RCC structure covering 30% area but The factory management did not agreement with any enlisted consultant firm. 18/11/2020 Visit Observation: This issue covered under DEA. Not started anything regarding this issue. No agreement done with any DIFE enlisted consulting firm to do the structural design & drawings. Now the factory management is instructed to do all structural design & মন্তব্য drawings along with DEA and the roof top shed by an enlisted firm of DIFE and submit them to DIFE RCC within 31/12/2020. 25/08/2021 Visit Observation: Same as previous. This issue covered under DEA. Not started anything regarding this issue. No agreement done with any DIFE enlisted consulting firm to do the structural design & drawings. Now the factory management is instructed to do all structural design & drawings along with DEA by an enlisted firm of DIFE and submit them to DIFE RCC within 25/09/2021.

২.২. কাৰ্যক্ৰম কাৰ্যক্ৰম Building Engineer to survey and prepare as-built drawings for the shed. |সপারিশের ভিখ্যসূত্র কারখানার কাৰ্যক্ৰম অগ্রাধিকার চুডান্ড | সময়সীমা সংশোধিত 07-07-7900 সময়সীমা অগ্রগতির শুরু হয়নি অবস্থা 24.08.20 Visit observation: No as built drawing has been prepared by the factory. 18/11/2020 Visit Observation: This issue covered under DEA. Not started anything regarding this issue. No agreement done with any DIFE enlisted consulting firm to do the structural design & drawings. Now the factory management is instructed to do all structural design & drawings along with DEA and the roof top shed by an enlisted firm of মন্তব্য DIFE and submit them to DIFE RCC within 31/12/2020. 25/08/2021 Visit Observation: Same as previous. This issue covered under DEA. Not started anything regarding this issue. No agreement done with any DIFE enlisted consulting firm to do the structural design & drawings. Now the factory management is instructed to do all structural design & drawings along with DEA by an enlisted firm of DIFE and submit them to DIFE RCC within 25/09/2021.