

## গণপ্রজাতন্ত্রী বাংলাদেশ সরকার শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোতন কর্মপরিবেশ; াড়ে জুলবে স্মার্ট বাংলাদেশ"

## ক্যাপ পর্ববেষ্ফণের তথ্য

কারখানার নাম	মেসাৰ্স পুৰাত্তন মৌতাৰা ফ্যাশন
ঠিকানা	Thokeyer Par, New Shayebgonj, Kotoali, Rangpur
কারখানার কোড	RNG001
কালার কোড	

মূল্যারনের ধরণ: কাঠামোগত মূল্যারন পর্ববেষ্ফণের তারিখ:			
১. পর্যবেষ্ফণ			
পরিদর্শন পর্যবেষ্ক্রণ Non engineered connection and bracing system ক্যাপ			
আইটেম ক্যাটাগরি			
১.১. কাৰ্যক্ৰম			
checked by building engineer. The bracing system কাৰ্শক্ষম required to ensure the stability of the shed building	The connection in between masonry wall and MS angle shed structure needs to be checked by building engineer. The bracing system and tie between purlin are required to ensure the stability of the shed building. Carry out the remedial actions as directed by the Building Engineer for non-engineered connection and bracing system.		
সুপারিশের ভখ্যসূত্র			
কার্থানার কার্থক্রম Action has not been taken but the factory have ag	Action has not been taken but the factory have agreed to complete this issue.		
<b>অগ্রাধিকার</b> প্রযোজ্য নয়			
চূড়ান্ত সম্বসীমা	08-08-20%9		
সংশোধিত সমশ্রসীমা			
্ষ্প্রগতির অবস্থা			