



গণপ্রজাতন্ত্রী বাংলাদেশ সরকার
শ্রম ও কর্মসংস্থান মন্ত্রণালয়
কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোভন কর্মপরিবেশ;
গড়ে তুলবে স্মার্ট বাংলাদেশ"

ক্যাপ পর্যবেক্ষণের তথ্য

কারখানার নাম	রোজ সুয়েটার লিঃ
ঠিকানা	Mogarkhal, Bijoy Sarak, Joydevpur, Gazipur
কারখানার কোড	GZP289
কালার কোড	
মূল্যায়নের ধরণ: কার্যামোগত মূল্যায়ন	পর্যবেক্ষণের তারিখ: ২৯-০৩-২০২৩
১. পর্যবেক্ষণ	

পরিদর্শন পর্যবেক্ষণ	No proper roof drainage and water proofing
কাপ আইটেম ক্যাটাগরি	

১.১. কার্যক্রম

কার্যক্রম	Proper roof drainage system and water proofing need to be implemented as per guidance of building engineer.
সুপারিশের তথ্যসূত্র	
কারখানার কার্যক্রম	We will engage a building engineer to implement proper roof drainage system & water proofing. 13th December 2020:
অগ্রাধিকার	প্রযোজ্য নয়
চূড়ান্ত সময়সীমা	০৭-১০-২০১৭
সংশোধিত সময়সীমা	০১-০১-১৯৭০
অগ্রগতির অবস্থা	চলমান
মন্তব্য	Water ponding has been observed on roof during site visit. 13th December 2020: Water ponding mark has been observed on roof. 06.06.2021: Water ponding on the rooftop was observed. 3rd August 2022: During visit day water ponding on the rooftop was observed. 29.03.2023: During visit day water ponding on the rooftop was observed.

সংযুক্তিসমূহ (৪)

