



গণপ্রজাতন্ত্রী বাংলাদেশ সরকার  
শ্রম ও কর্মসংস্থান মন্ত্রণালয়  
কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"শ্রমজীবী মানুষের অধিকার,  
বৈষম্যহীন বাংলাদেশের অঙ্গীকার"

ক্যাপ পর্যবেক্ষণের তথ্য

কারখানার নাম	রোজ সুয়েটার লিঃ
ঠিকানা	Mogarkhal, Bijoy Sarak, Joydevpur, Gazipur
কারখানার কোড	GZP289
কালার কোড	
মূল্যায়নের ধরণ: <a href="#">কঠামোগত মূল্যায়ন</a>	পর্যবেক্ষণের তারিখ: <a href="#">২৯-০৩-২০২৩</a>
১. পর্যবেক্ষণ	

পরিদর্শন পর্যবেক্ষণ	No proper roof drainage and water proofing
কাপ আইটেম ক্যাটাগরি	

#### ১.১. কার্যক্রম

কার্যক্রম	Proper roof drainage system and water proofing need to be implemented as per guidance of building engineer.
সুপারিশের তথ্যসূত্র	
কারখানার কার্যক্রম	We will engage a building engineer to implement proper roof drainage system & water proofing. 13th December 2020:
অগ্রাধিকার	প্রযোজ্য নয়
চূড়ান্ত সময়সীমা	০৭-১০-২০১৭
সংশোধিত সময়সীমা	০১-০১-১৯৭০
অগ্রগতির অবস্থা	চলমান
মন্তব্য	Water ponding has been observed on roof during site visit. 13th December 2020: Water ponding mark has been observed on roof. 06.06.2021: Water ponding on the rooftop was observed. 3rd August 2022: During visit day water ponding on the rooftop was observed. 29.03.2023: During visit day water ponding on the rooftop was observed.

#### সংযুক্তিসমূহ ( ৪ )

