

গণপ্রজাতন্ত্রী বাংলাদেশ সরকার শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোতন কর্মপরিবেশ; াড়ে জুলবে স্মার্ট বাংলাদেশ"

ক্যাপ পর্ববেষ্ফণের তথ্য

কারখানার নাম	এমটিএম গার্মেন্ট্স
115/401611	Holding- 15934/16004, Chandpara, Medical road, Uttarkhan, Dhaka Bangladesh
কারখানার কোড	DHK 391
কালার কোড	

মুল্যায়নের ধরণ: কাঠামোগত মুল্যায়ন	পর্ববেষ্ফণের তারিখ: 🕒
১. পর্যবেষ্ষণ	
পরিদর্শন পর্যবেষ্ক্রণ Roof drainage and water proofing system	
ক্যাপ আইটেম ক্যাটাগরি	
১.১. কাৰ্যক্ৰম	
Water proofing and proper roof drainage system directed by the guidance of building engineer.	need to be implemented as
সুপারিশের তথ্যসূত্র	
কাৰ্শানাৰ কাৰ্শক্ষম Initiative has not been taken yet but they have	agreed to complete within timeline
অগ্রাধিকার প্রয়োজ্য নয়	
চূড়ান্ত সম্বসীমা	
সংশোধিত সম্বসীমা	
্ষাপ্রাক্তির অবস্থা	
On:28.01.2020: Factory found shifted/closed. O water proofing system has been not started yet. started anything regarding this issue. The factor solve this issue within 01/05/2021. 18.08.21 Vis management did not take any action about this	On Visit date 29/03/2021: Not ry management is instructed to it observation:The factory

২. পর্ববেষ্ণণ

পরিদর্শন পর্শবেষ্ফণ	Exposed rebar
ক্যাপ আইটেম ক্যাটাগরি	İ

হিxposed reinforcement need to be covered by lean graded concrete following the guidance of Building Engineer. মুপানিশেন ভখ্যমুত্ৰ কানখানান কাৰ্যক্ৰম Initiative has been taken and completed অগ্লাধিকান প্ৰযোগ্য ল্য চুড়ান্ত মন্যমীমা সংশোধিজ সময়মীমা ত ১০০১০১১৭০

প্রবিষ্টা

On:28.01.2020: Factory found shifted/closed. On 07.12.2020: Exposed rebar has been found on roof. No initiative has been taken for this issue. On Visit date 29/03/2021: This issue found completed on the visiting date by paint. 18.08.21 Visit observation:This issue found completed on the visiting date by paint.

অগ্রগতির

সংশোধিত