



গণপ্রজাতন্ত্রী বাংলাদেশ সরকার  
শ্রম ও কর্মসংস্থান মন্ত্রণালয়  
কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোভন কর্মপরিবেশ;  
গড়ে তুলবে স্মার্ট বাংলাদেশ"

ক্যাপ পর্যবেক্ষণের তথ্য

কারখানার নাম	মাসকো পিকাসো লিমিটেড
ঠিকানা	318, KHAPARI ROAD, SHATAISH, TONGI, Gazipur
কারখানার কোড	GZP218
কালার কোড	
মূল্যায়নের ধরণ: <a href="#">কাঠামোগত মূল্যায়ন</a>	পর্যবেক্ষণের তারিখ: ১৭-১১-২০২২
১. পর্যবেক্ষণ	

পরিদর্শন পর্যবেক্ষণ	Soil test report and floor load plan were not available.
কাপ আইটেম কাটাগরি	

### ১.১. কার্যক্রম

কার্যক্রম	Building engineer should investigate the soil vicinity to the structure. He also should prepare a floor load plan.
সুপারিশের তথ্যসূত্র	
কারখানার কার্যক্রম	Soil test report has been prepared and floor load plan will be prepared by the Engineer.
অগ্রাধিকার	প্রযোজ্য নয়
চূড়ান্ত সময়সীমা	০২-০২-২০১৭
সংশোধিত সময়সীমা	০১-০১-১৯৭০
অগ্রগতির অবস্থা	চলমান
মন্তব্য	02.09.2021: Soil test report, Material test report, building approval plan from local government authority, as built architectural drawing, as built structural drawing were found in factory. Load plan found but not vetted. Factory consultant were not nominated by DIFE. 17/11/2022: All Design & Drawing should be submitted to DIFE for approval as soon as possible.

### সংযুক্তিসমূহ ( ৪ )

