

গণপ্রজাতন্ত্রী বাংলাদেশ সরকার শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"শ্রমজীবী মানুষের অধিকার, বৈৰম্যাহীন বাংলাদেশের অঙ্গীকার"

ক্যাপ পর্ববেষ্ফণের তথ্য

কারখানার নাম	মাসকো পিকাসো লিমিটেড
ঠিকানা	318, KHAPARI ROAD, SHATAISH, TONGI, Gazipur
কারখানার কোড	GZP 218
কালার কোড	

মুল্যায়নের ধরণ: কাঠামোগত মুল্যায়ন	পর্ববেষ্ফণের তারিখ: ১৭–১১–২০২২
১. পর্যবেষ্ণ	

পরিদর্শন পর্শবেষ্ণণ	Soil test report and floor load plan were not available.
ক্যাপ জ্যান্ট ে ম	
আখ্ডেশ ক্যাটাগরি	r

১.১. কাৰ্যক্ৰম

	,
কাৰ্শক্ৰম	Building engineer should investigate the soil vicinity to the structure. He also
	should prepare a floor load plan.
সুপারিশের	
ভ৾খ্যসূত্ৰ	
কারখানার	Soil test report has been prepared and floor load plan will be prepared by the
কাৰ্যক্ৰম	Engineer.
<u>অগ্রা</u> খিকার	প্রবোজ্য নয়
চুডান্ত	02-02-20%9
<u> </u>	04-04-4024
সংশোধিত	02-02-229
সমশ্বসীমা	02-02-2040
<u>অগ্রগতির</u>	চলমান
অবস্থা	
মন্তব্য	02.09.2021: Soil test report, Material test report, building approval plan from local
	government authority, as built architectural drawing, as built structural drawing
	were found in factory. Load plan found but not vetted. Factory consultant were not
	nominated by DIFE. 17/11/2022: All Design & Drawing should be submitted to DIFE
	for approval as soon as possible.

সংযুক্তিসমূহ (৪)





