



গণপ্রজাতন্ত্রী বাংলাদেশ সরকার  
শ্রম ও কর্মসংস্থান মন্ত্রণালয়  
কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"শ্রমজীবী মানুষের অধিকার,  
বৈষম্যহীন বাংলাদেশের অঙ্গীকার"

ক্যাপ পর্যবেক্ষণের তথ্য

কারখানার নাম	শাদ নিটওয়ার লি:
ঠিকানা	Arabari, Mouchak, Gazipur
কারখানার কোড	GZP294
কালার কোড	
মূল্যায়নের ধরণ: <a href="#">কঠামোগত মূল্যায়ন</a>	পর্যবেক্ষণের তারিখ: <a href="#">১১-০৪-২০২৩</a>
১. পর্যবেক্ষণ	

পরিদর্শন পর্যবেক্ষণ	Exposed rebar has been found on roof top.
কাপ আইটেম ক্যাটাগরি	

#### ১.১. কার্যক্রম

কার্যক্রম	All of the exposed rebars to be coated with proper weather coating.
সুপারিশের তথ্যসূত্র	
কারখানার কার্যক্রম	[Whom is going to carry out the recommendation?] [How will the recommendation be carried out?]
অগ্রাধিকার	১ সপ্তাহ
চূড়ান্ত সময়সীমা	০১-০১-১৯৭০
সংশোধিত সময়সীমা	০৫-০৩-২০২৩
অগ্রগতির অবস্থা	চলমান
মন্তব্য	27.09.2020: Exposed rebar has been found on roof top column and stair with coating but not with red oxide. Also the staircase rebars are not coated. 13 January 2021: Exposed rebar has been found on roof top column and stair with coating but not with red oxide. Also the staircase rebars are not coated. 03.06.2021: Exposed rebars were still not painted or coated. 16.08.2022: Roof top column exposed rebars & expose rebar of stair were still not painted or coated. 11.04.2023: Roof top column exposed rebars & expose rebar of stair were still not painted or coated.

#### সংযুক্তিসমূহ ( ৪ )

