গণপ্রজাতন্ত্রী বাংলাদেশ সরকার শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর



"শ্রমজীবী মানু্বের অধিকার, বৈষ্দ্যাহীন বাংলাদেশের অঙ্গীকার"

<u>ক্যাপ পর্ববেষ্ষণের তথ্য</u>

কারখানার নাম	এফ আৰ এম ফ্যাশন হাউজ লি:
ঠিকানা	226 Singair Road, Hemayetpur, Savar, Dhaka
কারখানার কো	ס DHK217
কালার কোড	
মন্যায়নের ধরন	: কাঠামোগত মল্যায়ন পর্যবেষ্ণ্ডণের তারিখ: ১৮–০৫–২০২২
	: কাঠামোগত মুল্যায়ন পর্ববেষ্ণণের তারিখ: ১৮–০৫–২০২২
১. পর্শবেষ্ষণ	
পরিদর্শন 📖	ably strassed column
পর্ববেষ্ষণ ⊓।	ghly stressed column
ক্যাপ	
আই্টেম্	
ক্যাটাগরি	
	•
১.১. কাৰ্শক্ৰম্	
	Factory Engineer to review design, loads and columns stresses in area identified
কাৰ্শক্ৰম	above.
সুপারিশের	
🛛 🖉 তিথ্যসুত্র	
কারখানার	
কাৰ্শক্ৰম	
	প্রযোগ্য লয়
চুডান্ত	_
<u>স্মির্মীমা</u>	
সংশোধিত সালকীস	0 2 - 0 2 - 2 2 9 0
সমরসীমা অগ্রগতির	
অবস্থা আবস্থা	সংশোধিত্ত
জব [্] থ মন্তব্য	On visit date 22/02/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. Now the factory management is instructed to submit all ACCORD approved design & drawings with soft copy CD and ACCORD CAP completion certificate to DIFE RCC within 22/03/2021. On Visit Date 31/08/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. They've submitted all ACCORD approved structural design & drawings to DIFE RCC on 03/03/2021. Now the factory management is waiting for taskforce decision from DIFE RCC.

পরিদর্শন পর্যবেষ্ণ্যণ	
ক্যাপ আইটেম ক্যাটাগরি	

কাৰ্শক্ৰম	Verify in-situ concrete stresses by 100mm dia. cores from C2 Column.
সুপারিশের	
ভঁখ্যসুত্র	
কার্খানার	
<u>কাৰ্শক্ৰম</u>	
	প্রযোগ্য নর
চুডান্ড সময়সীমা	_
সংশোধিত্ত সমশ্রসীমা	o?-o?-?9do
অগ্রগতির	সংশোধিত্ত
অবস্থা	
মন্তব্য	On visit date 22/02/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. Now the factory management is instructed to submit all ACCORD approved design & drawings with soft copy CD and ACCORD CAP completion certificate to DIFE RCC within 22/03/2021. On Visit Date 31/08/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. They've submitted all ACCORD approved structural design & drawings to DIFE RCC on 03/03/2021. Now the factory management is waiting for taskforce decision from DIFE RCC.

৩. পর্যবেষ্ষণ

পরিদর্শন পর্শবেষ্ষণ	Highly stressed column
ক্যাপ আই্টেম্	
ক্যাটাগৰি	í

.১. কাৰ্শক্ৰ	স
কাৰ্শক্ৰম	A Detail Engineering Assessment of Factory to be commenced, see attached Scope.
সুপারিশের তথ্যসুত্র	
কার্থানার	
কাৰ্শক্ৰম অগ্ৰাধিকাৰ	প্রযোগ্য লয়
<u>চ</u> ুডান্ত সমর্যসীমা	
সংশোধিত্ত সমর্যসীমা	o?-o?-??Jo
অগ্রগতির অবস্থা	সংশোধিত্ত
মন্তব্য	On visit date 22/02/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. Now the factory management is instructed to submit all ACCORD approved design & drawings with soft copy CD and ACCORD CAP completion certificate to DIFE RCC within 22/03/2021. On Visit Date 31/08/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. They've submitted all ACCORD approved structural design & drawings to DIFE RCC on 03/03/2021. Now the factory management is waiting for taskforce decision from DIFE RCC. 18-05-2022 (CCVV): 4 nos. ancillary structures (Dining Shed, Generator Room, Admin Room and Inspection Room) have been found in the factory premises., which have only as-built drawing without any DEA report.

ক্যাপ আই্টেম্	পরিদর্শন পর্ববেষ্ষণ	Highly stressed column
किंगानुसार	ক্যাপ আইট্টেম ক্যাটাগ্রবি	

	Produce and actively manage a loading plan for all floor plates within the factory
কাৰ্শক্ৰম	giving consideration to floor capacity and column capacity.
সুপারিশের তথ্যসুত্র	
কার্য্থানার কার্শক্রম	
অগ্রাধিকার	প্রযোগ্য নর
চুডান্ড <u>সমর্য</u> মীমা	-
সংশোধিত্ত সমর্যসীমা	o7-o7-79do
অগ্রগতির অবস্থা	সংশোধিত
মন্তব্য	On visit date 22/02/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. Now the factory management is instructed to submit all ACCORD approved design & drawings with soft copy CD and ACCORD CAP completion certificate to DIFE RCC within 22/03/2021. On Visit Date 31/08/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. They've submitted all ACCORD approved structural design & drawings to DIFE RCC on 03/03/2021. Now the factory management is waiting for taskforce decision from DIFE RCC.

৫. পর্ববেষ্ণণ

পরিদর্শন পর্ববেক্ষণ	
ক্যাপ আইটেম্]
ক্যাটাগরি	

কাৰ্শক্ৰম	Detail Engineering Assessment to be completed.
সুপারিশের	
<u> তথ্যসুত্র</u>	
কার্শানার	
কাৰ্শজ্ৰম	
	প্রযোগ্য নর
চুডান্ত <u>সমর্যনীমা</u>	_
সংশোধিত্ত <u>সমশ্রসীমা</u>	०१-०१-११४०
অগ্রগতির অবস্থা	সংশোধিত
মন্তব্য	On visit date 22/02/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. Now the factory management is instructed to submit all ACCORD approved design & drawings with soft copy CD and ACCORD CAP completion certificate to DIFE RCC within 22/03/2021. On Visit Date 31/08/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. They've submitted all ACCORD approved structural design & drawings to DIFE RCC on 03/03/2021. Now the factory management is waiting for taskforce decision from DIFE RCC.

৬. পর্যবেষ্ষণ

পরিদর্শন পর্ববেষ্ষণ	Highly stressed column
ক্যাপ আইট্টেম	
ক্যাটাগরি	

কাৰ্শক্ৰম	Continue to implement load plan.
<u>সু</u> পারিশের	
<u>ত</u> থ্যসূত্র	
কার্ঝানার	
কাৰ্শক্ৰম	
অগ্রাধিকার	প্রব্যোচ্য লয়
চুডান্ত সমর্যসীমা	_
সংশোধিত্ত সমর্যসীমা	०७-०१-१२४०
অগ্রগতির অবস্থা	সংশোধিত্ত
মন্তব্য	On visit date 22/02/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. Now the factory management is instructed to submit all ACCORD approved design & drawings with soft copy CD and ACCORD CAP completion certificate to DIFE RCC within 22/03/2021. On Visit Date 31/08/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. They've submitted all ACCORD approved structural design & drawings to DIFE RCC on 03/03/2021. Now the factory management is waiting for taskforce decision from DIFE RCC.

৭. পর্ববেষ্ষণ

পরিদর্শন পর্শবেষ্ষণ	Lateral Stability System Not Apparent
ক্যাপ আইট্েম ক্যাটাগরি	

n.১. কাৰ্বজম	
কাৰ্শক্ৰম	Factory Engineer to review design, loads and punching capacity for slabs. Carry out any remedial actions as directed by the Building Engineer for lateral stability system.
সুপারিশের তথ্যসুত্র	
কার্য্থীনার কার্শক্রম	
	প্রযোজ্য নয়
চুডান্ড সময়সীমা	_
সংশোধিত্ত সমশ্রসীমা	0 / - 0 / - 2 0
অগ্রগতির অবস্থা	সংশোধিত
মন্তব্য	On visit date 22/02/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. Now the factory management is instructed to submit all ACCORD approved design & drawings with soft copy CD and ACCORD CAP completion certificate to DIFE RCC within 22/03/2021. On Visit Date 31/08/2021: The factory management have done all Structural remediation works under ACCORD supervision. ACCORD's Structural CAP completion certificate with all design & drawings found during visit. They've submitted all ACCORD approved structural design & drawings to DIFE RCC on 03/03/2021. Now the factory management is waiting for taskforce decision from DIFE RCC. 18–05–2022 (CCVV): Possible over loading has been found at ground floor.
भः शुष्ठिम्	지정 (2) ····································