

গণপ্রজাতন্ত্রী বাংলাদেশ সরকার

শ্রম ও কর্মসংস্থান মন্ত্রণালয় কলকারখানা ও প্রতিষ্ঠান পরিদর্শন অধিদপ্তর

"সুস্থ শ্রমিক, শোভন কর্মপরিবেশ; গড়ে জুলবে স্মার্ট বাংলাদেশ"

ক্যাপ পর্ববেষ্কণের তথ্য

কারখানার নাম	তুইশা
ঠিকানা	Rupshi, Rupganj, Narayanganj
কারখানার কোড	NRY044
কালার কোড	

ଧୂ୍ଜା ୟ(ଶ୍ୟ ଅୟମ: ବାଧା(ଧାର୍ଗର ଧୂଜା ୟଶ	পুৰ বেশ্চ গেৰ জ্বাৰিখ: ১২ – ০২ – ২০২জ							
১. পর্যবেষ্ণ্যণ								
পরিদর্শন Steel or temporary structure not conforr পর্শবেষ্ণণ building.	ming to Type-I construction on Roof-top of							
ক্যাপ আইটেম ক্যাটাগরি								

Remove temporary structure from roof top

১.১. কাৰ্যক্ৰম

কাৰ্যক্ৰম

সুপারিশের তথ্যসূত্র

কার্থানার কার্বক্রম	We have already removed structure from roof top			
অগ্রাধিকার	প্রব্যোগ্য নয়			
চুডান্ড সমশ্রসীমা	o & - o B - 2 o 2 2			
সংশোধিত সময়সীমা				
অগ্রগতির অবস্থা	চলমান			
মন্তব্য	04.10.2020:Found temporary structure but they were removed half portion. 25–01–2021: The factory authority did not agree to remove full portion of steel temporary structure, yet we found half potion already removed. 03.09.2022: Non engineering Steel shed or temporary structure has been found on roof top during visit day which are not incorporate in DEA report. They were removed half portion. 12.02.2023: Non engineering Steel shed or temporary structure has been found on roof top during visit day which are not incorporate in DEA report. They were removed half portion.			

সংশুক্তিসমূহ (৪)





